



Inspection Report

Inspection Date: 2024/11/29

Excavators

General Information

Maker	KOMATSU		
Model Number	PC78UU-8		
Year	2012		
Hour (h)	5188	Meter	Working
Serial Number	18499		

Options


- CAB	- Speed changer
	- Air conditioner
- Blade	
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	630			

Note for External Appearance

- The body has some rust and scratches



Undercarriage


Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	450	450	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure



Note for Undercarriage

- The rubber pads are missing



Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for Operating Component



Note for Engine



Admin No. 3000066783