



# Inspection Report

Inspection Date:

#N/A

## General Information

<b>Maker</b>	SAKAI
<b>Model Number</b>	HV60ST
<b>Year</b>	2004
<b>Hour (h)</b>	
<b>Serial Number</b>	VHV12-42933

## Engine

<b>Model</b>	NFAD6-ESA
<b>Serial Number</b>	072369
<b>Engine Oil Leak</b>	Oil oozing
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	OK
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

## Note for External Appearance

- The vibrating operation and the forward/ backward traveling operation have been checked to be in normal condition.
- The battery is flat; operating condition was checked with booster cables connected
- The cover has rusty and some scratches

## Note for Control Panel

## Note for Engine

## Other Information

Admin. No. 3000067310

\*This report is only for your reference. We are not responsible for the actual condition of checked item.