



Inspection Report

Inspection Date: 2024/12/13

Excavators

General Information

Maker	KOMATSU		
Model Number	PC78US-6NO		
Year	2007		
Hour (h)	4775	Meter	Working
Serial Number	KMTPC030E01011049		

Options


- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	- Breaker Pipings
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	630			

Note for External Appearance

- Repainted
- The body has some scratches and rust



Undercarriage

Shoe Type	Steel		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	450	450	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	


Note for Upper Structure

- The arm has been reinforced



Note for Undercarriage

--



Engine

Model	S4D95LE-3
Serial Number	121027
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Not enough cooling water
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

--



Note for Engine

--



Admin No. 3000067375