

Inspection Date: 2021/05/08

General Information		
Maker	CAT	
Model Number	320D	
Year	2009	
Hour (h)	10308 <b>Meter</b>	Working
Serial Number	CAT0320DLBWZ03536	

Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	
- EPA	

Upper Structure				
		Cylinder		Play
			Scratch/Rust	
Boom	Left	Oil leak	No	No
	Right	Oil leak	No	140
	Arm	No	No	No
Bucket		No	No	Big
Bucket Siz	ze (mm)	1200		

		Cylinder		Play
		Oil Leak	Scratch/Rust	riay
Boom	Left	Oil leak	No	No
	Right	Oil leak	No	INO
Arm		No	No	No
Bucket		No	No	Big
Bucket Siz	ze (mm)	) 1200		

Undercarriage		
Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	800	800
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Undercarriage			
Shoe Type	Steel		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	800	800	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	

Engine	
Model	C6.4
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	ОК
Radiator	ОК
Exhaust Color	Normal
Blow-by	No
Engine Sound	ОК
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	Oil oozing

Note for External Appearance	
The body is partly rusty, damaged, and decayed	





## Note for Operating Component - Reversible fan alert; please check the - Crane mode error; please check the photos - The seat is partly torn Note for Engine

Admin No.

3000031098