



Inspection Report

Inspection Date: 2024/08/23

Excavators

General Information

Maker	YANMAR		
Model Number	ViO70-3A		
Year	2012		
Hour (h)	4636	Meter	Working
Serial Number	37050		

Options


- CAB	- Speed changer
	- Air conditioner
- Blade	- Piping
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	645			

Note for External Appearance

- The body is deteriorated and rusted over time




Undercarriage

Shoe Type	Steel		
Swing Circle	Oil oozing		
		Left	Right
Shoe Width (mm)	600	600	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure

- The bucket side cutters are missing



Note for Undercarriage



Engine

Model	4TNV98-ZWBV
Serial Number	L6232
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn



Note for Engine



Admin No. 3000062805