



# Inspection Report

Inspection Date: 2020/02/04

## Excavators

### General Information

Maker	YANMAR		
Model Number	VIO30-2		
Year			
Hour (h)	2808	Meter	Working
Serial Number	22518B		

### Options

- CNP	- Speed changer
- Multilever	
- Blade	- Pippings

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil leak	Yes	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		470		

### Note for External Appearance

- The boom cylinders are rusty
- The blade and undercarriage are rusty and decayed
- Concrete adheres to the bucket



### Note for Upper Structure



### Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

### Note for Undercarriage

The undercarriage is rusty and decayed



### Engine

Model	
Serial Number	72844
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

### Note for Operating Component



### Note for Engine

Oil oozing



Admin No. 3000000677