



Inspection Report

#REF! 2021/12/10

Crawler Dumper

General Information

Maker	HITACHI
Model Number	EG110R
Year	2005
Hour (h)	9420
Serial Number	HCM81T00L00010167

Note for External Appearance

- Could not find the VIN

Engine

Model	AA-6HK1XQA
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

Note for Engine

Other Information

- CAB
- Oil oozing from the right reduction drive
- The cargo bed is rusty and dented

Admin. No. 3000037098

*This report is only for your reference. We are not responsible for the actual condition of checked item.