



Inspection Report

Inspection Date:

Aerial Work Platform

General Information

Maker	AICHI
Model Number	SR18A
Year	2007
Hour (h)	6624
Serial Number	709329

Note for External Appearance

- Repainted
- The body has rusty
- The cover and guard of the upper control panel are damaged

Engine

Model	4JG1
Serial Number	332473
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	Unchecked
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

- The engine won't stop with the key ignition; the stop solenoid must be operated manually

Note for Engine

- EPA

Other Information

- Some of the right shoes have kinks

Admin. No. 3000084524

*This report is only for your reference. We are not responsible for the actual condition of checked item.