



Inspection Report

Inspection Date: 2018/12/06

Excavators


General Information			
Maker	KUBOTA		
Model Number	U-20-3S		
Year			
Hour (h)	1751	Meter	Working
Serial Number	17439		

Options	
- CNP	- Speed changer
- Blade	- Breaker Pipings

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		400		

Note for External Appearance


- The engine cover has some dents and scratches
- The roof of the canopy is partly damaged
- One of the bolts of the canopy was lost



Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	250	250	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	


Note for Upper Structure

Complete washing is not applicable (bucket)




Note for Undercarriage

The rubber shoes have deteriorated over time and are partly worn




Engine	
Model	
Serial Number	1EY6639
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for Operating Component



Note for Engine

Engine backlash noise is loud while idling



Admin No. 2018110347