



Inspection Report

Inspection Date: 2026/07/18

Excavators

General Information

#ERROR!	HITACHI		
Model Number	ZX225USR-6		
Year	2018		
Hour (h)	6364	Meter	Working
Serial Number	HCMDFCA2A00501286		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
	- Pippings
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		1020		

Note for External Appearance

- Repainted
- The body has some scratches and rust



Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	600	600
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

- The left shoe travel is slightly weak.



Engine

Model	AR-4HK1XASA-12	
Serial Number	765907	
Engine Oil Leak	No oil leak	
Engine Oil Gauge	OK	
Radiator	Not enough cooling water	
Exhaust Color	Normal	
Blow-by	No	
Engine Sound	OK	
Hydraulic Pump	No oil leak	
Water Pump	No water leak	
Oil Cooler	No oil leak	
Motor	No oil leak	
Multi Lever	No oil leak	

Note for Operating Component



Note for Engine



Admin No. 3000087737

*This report is only for your reference. We are not responsible for the actual condition of checked item.