



Inspection Report

Inspection Date: 2023/12/02

Excavators

General Information

| | | | |
|----------------------|--------|--------------|---------|
| Maker | YANMAR | | |
| Model Number | B30U | | |
| Year | 2017 | | |
| Hour (h) | 1517 | Meter | Working |
| Serial Number | 5F107 | | |

Options

- | | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | |
| - Arm Crane | |

Upper Structure

| | | Cylinder | | Play |
|------------------|-------|----------|--------------|-------|
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | Small |
| | Right | N/A | N/A | |
| Arm | | No | No | Small |
| Bucket | | No | Yes | Small |
| Bucket Size (mm) | 400 | | | |

Note for External Appearance

- The right side of the body has dents and scratches



Undercarriage

| Shoe Type | Rubber | |
|---------------------|-------------|-------|
| Swing Circle | No oil leak | |
| | Left | Right |
| Shoe Width (mm) | 300 | 300 |
| Idler | OK | OK |
| Sprocket | OK | OK |
| Pin Bush | OK | OK |
| Upper Roller | OK | OK |
| Track Roller | OK | OK |
| Shoe Link | OK | OK |

Note for Upper Structure



Note for Undercarriage



Engine

| | |
|-------------------------|---------------|
| Model | 3TNV82A-BPYBU |
| Serial Number | F5481 |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | No oil leak |

Note for Operating Component



Note for Engine



Admin No. 3000053520