



Inspection Report

Inspection Date: 2018/09/29

Generator

General Information

Maker	DENYO
Model Number	DCA-125ESM
Year	
Hour (h)	1264
Serial Number	3718369

Note for External Appearance

- The paint has deteriorated over time
- The top plate near the muffler is partly deformed

Engine

Model	6D16-TLE2B
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	Oil shortage
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

Note for Engine

Admin. No. 2018090366

*This report is only for your reference. We are not responsible for the actual condition of checked item.