



# Inspection Report

Inspection Date: 2021/05/08

## Excavators

### General Information

<b>Maker</b>	CAT		
<b>Model Number</b>	320D-E		
<b>Year</b>	2009		
<b>Hour (h)</b>	11165	<b>Meter</b>	Working
<b>Serial Number</b>	CAT0320DPBWZ04127		

### Options


- CAB	- Speed changer
- Multilever	- Air conditioner
	- PIPINGS
- EPA	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		Oil oozing	No	No
Bucket		No	No	No
Bucket Size (mm)	1020			

### Note for External Appearance

- The body is partly rusty and damaged




### Undercarriage

<b>Shoe Type</b>	Steel	
<b>Swing Circle</b>	No oil leak	
	<b>Left</b>	<b>Right</b>
<b>Shoe Width (mm)</b>	800	800
<b>Idler</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Pin Bush</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Track Roller</b>	OK	OK
<b>Shoe Link</b>	OK	OK

### Note for Upper Structure

- Oil oozing from the control valve



### Note for Undercarriage




### Engine

<b>Model</b>	C6.4
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	Oil oozing
<b>Engine Oil Gauge</b>	Oil shortage
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component

- The seat is partly torn



### Note for Engine



Admin No. 3000031101