



Inspection Report

Inspection Date: 2023/09/07

Excavators

General Information

Maker	KOBELCO		
Model Number	SK135SR-2		
Year	2007		
Hour (h)	7678	Meter	Working
Serial Number	YT05-12066		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
	- Pipings
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	Oil oozing	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		890		

Note for External Appearance



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	500	500
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

- Many rubber pads are partly chipped or broken



Engine

Model	D04FR-KDP2TAAC
Serial Number	D04FR-000242
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn



Note for Engine

- Fuel leaks from the engine



Admin No. 3000051047

*This report is only for your reference. We are not responsible for the actual condition of checked item.