



Inspection Report

Inspection Date: 2024/06/13

Excavators

General Information

Maker	KUBOTA		
Model Number	U-30-5		
Year	2008		
Hour (h)	6161	Meter	Working
Serial Number	71124		

Options


- CAB	- Speed changer
- Multilever	
- Blade	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)				

Note for External Appearance

- No VIN plate
- No bucket
- Oil oozing from the bottom



Undercarriage

Shoe Type	Rubber	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	495	495
Idler	OK	OK
Sprocket	NG	NG
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- The boom cylinder is rusted



Note for Undercarriage

--



Engine

Model	D1703
Serial Number	8J2506
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn



Note for Engine

--



Admin No. 3000059319