



Inspection Report

Inspection Date: 2019/07/10

Excavators

General Information

Maker	KOBELCO		
Model Number	SK30UR-6		
Year	2015		
Hour (h)	566	Meter	Working
Serial Number	R10138		

Options

- CNP
- Multilever
- Blade
- Arm Crane

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)	450			

Note for External Appearance

- The bucket is not clean
- Operational condition was not checked because there was not enough space for inspection



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage



Engine

Model	3TNV82A-BPYBU
Serial Number	D8383
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 2019070555