



Inspection Report

Inspection Date: 2024/08/24

Excavators

General Information

Maker	KUBOTA		
Model Number	U-40-6E		
Year	2016		
Hour (h)	4147	Meter	Working
Serial Number	30117		

Options

- CAB	- Speed changer
- Multilever	
- Blade	- Pippings
- Arm Crane	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		Oil oozing	No	Big
Bucket Size (mm)	545			

Note for External Appearance



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	350	350
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- The tip of the arm has some dents



Note for Undercarriage



Engine

Model	D1803
Serial Number	D1803 7GS6989
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Oil leak
Multi Lever	No oil leak

Note for Operating Component

- With air blower and heater



Note for Engine



Admin No. 3000062506