



Inspection Report

Inspection Date: 2024/12/02

Excavators

General Information

| | | | |
|----------------------|--------|--------------|---------|
| Maker | YANMAR | | |
| Model Number | SV05 | | |
| Year | 2005 | | |
| Hour (h) | 975 | Meter | Working |
| Serial Number | 00787B | | |

Options


| | |
|---------|--|
| - Blade | |
| - EPA | |

Upper Structure

| | | Cylinder | | Play |
|------------------|-------|----------|--------------|-------|
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | Small |
| | Right | No | No | |
| Arm | | No | No | Small |
| Bucket | | No | No | Small |
| Bucket Size (mm) | 280 | | | |

Note for External Appearance

- Repainted
- The body is rusty and has some scratches



Undercarriage

| Shoe Type | Rubber | | |
|---------------------|-------------|------|-------|
| Swing Circle | No oil leak | | |
| | | Left | Right |
| Shoe Width (mm) | 150 | 150 | |
| Idler | OK | OK | |
| Sprocket | OK | OK | |
| Pin Bush | OK | OK | |
| Upper Roller | OK | OK | |
| Track Roller | OK | OK | |
| Shoe Link | OK | OK | |

Note for Upper Structure



Note for Undercarriage



Engine

| | |
|-------------------------|---------------|
| Model | |
| Serial Number | |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | - |

Note for Operating Component



Note for Engine



Admin No. 3000066794