



Inspection Report


Inspection Date: 2018/08/06

Excavators


General Information			
Maker	HITACHI		
Model Number	ZX200LC-3		
Year	2009		
Hour (h)		Meter	Working
Serial Number	HCM1U100A00212146		


Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		1140		


Note for External Appearance


Undercarriage		
Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	700	700
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	NG	NG
Shoe Link	OK	OK

Note for Upper Structure


Note for Undercarriage
The surfaces of the truck frames are partly rusty


Engine	
Model	AI-4HK1XYSA-02
Serial Number	4HK1-448536
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
- Unable to read the hour meter (10? 33h)
- The monitor is broken


Note for Engine


Admin No. 2018080006