



Inspection Report

Inspection Date: 2025/11/28

Roller

General Information

Maker	KOMATSU
Model Number	JV40CW-2A
Year	1994
Hour (h)	3092
Serial Number	3092

Note for External Appearance

- Repainted
- The cover is rusty and has some scratches




Engine

Model	3D84N-2C
Serial Number	64845
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Note for Undercarriage

- Oil sprayer has damaged



Note for Operating Component

Note for Engine

- The battery is flat; it starts with booster cables



Admin. No. 3000079342

*This report is only for your reference. We are not responsible for the actual condition of checked item.