



Inspection Report

Inspection Date: 2021/01/30

Wheel Loader

General Information

Maker	KOMATSU
Model Number	520
Year	1984
Hour (h)	206
Serial Number	04A-10536

Note for External Appearance

- Temporary de-registration certificate will be ready 2 weeks after the auction ends
- CAB
- Piping



Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Note for Upper Structure



Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

Note for Operating Component

- Tachometer: 21,330km



Engine

Model	6D105-1
Serial Number	6D105-68682
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Note for Undercarriage

- Tire size: 14.00-24 12PLY



Documents

Automobile Inspection Certificate	Yes
------------------------------------------	-----

Note for Engine



Admin. No. 3000022573

*This report is only for your reference. We are not responsible for the actual condition of checked item.