



Inspection Report


Inspection Date: 2019/01/08

Excavators


General Information			
Maker	SUMITOMO		
Model Number	SH225TN-3		
Year			
Hour (h)	6045	Meter	Working
Serial Number	1103		

Options	
- CNP	
	- Breaker Pipings

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)				


Note for External Appearance
- The body is rusty - Tunnel type


Undercarriage			
Shoe Type	Steel		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	600	600	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
Short reach


Note for Undercarriage


Engine	
Model	
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
The canopy is partly rusty


Note for Engine


Admin No. 2018120342