



Inspection Report

Inspection Date: 2024/07/12

Excavators

General Information

Maker	KUBOTA		
Model Number	U-20-3S		
Year	2013		
Hour (h)	3540	Meter	Working
Serial Number	15362		

Options

- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)	400			

Note for External Appearance

- Repainted



Undercarriage

Shoe Type	Rubber		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	250	250	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure

- No side cutter



Note for Undercarriage



Engine

Model	
Serial Number	1DM1053
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000060229