Inspection Report

Inspection Date:

Carrier Dump

General Information

Maker	KUBOTA
Model Number	RG30C-3
Year	2011
Hour (h)	1
Serial Number	20125

Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	Not enough cooling water
Water Pump	No water leak
Injection Pump	No fuel leak

Note for External Appearance

- The cover has some scratches, rust, and corrosion
- The VIN stamp on the body was unchecked

Note for Control Panel

- The travel lever is slightly stuck
- The hour meter has been replaced

Note for Engine

Other Information

Admin. No. 3000091516

*This report is only for your reference. We are not responsible for the actual condition of checked item.