



Inspection Report

Inspection Date: 2021/04/21

Motor Grader

General Information

Maker	KOMATSU
Model Number	GD605A-5E
Year	1996
Hour (h)	10304
Serial Number	G60A5-1607

Engine

Model	6D125E-2-A
Serial Number	66647
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for External Appearance

- The body is rusty and damaged
- The body is not the original color

Note for Control Panel

- Mileage: 41,462km

Note for Engine

- Oil oozing from the engine

Other Information

- Oil oozing from the leaning cylinder
- Oil oozing from the left control valve
- Oil leak from the tandems
- The front right hub bearing is damaged according to the seller
- 6 of the tires are worn

Admin. No. 3000030701

*This report is only for your reference. We are not responsible for the actual condition of checked item.