



Inspection Report

Inspection Date: 2019/02/18


Excavators

General Information			
Maker	CAT		
Model Number	311CU		
Year	2005		
Hour (h)		Meter	Working
Serial Number	CLK03193		

Options	
- CAB	- Air conditioner
- Multilever	- Pipings


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		810		

Note for External Appearance




Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	500	500	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure




Note for Undercarriage
Oil oozing from around the swivel



Engine	
Model	BLK39898
Serial Number	G3420-64
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
- The seat is partly torn
- True hour unknown (159h+?)



Note for Engine



Admin No. 2019020331