



Inspection Report

Inspection Date: 2019/01/11


Excavators

General Information			
Maker	YANMAR		
Model Number	ViO30-5B		
Year	2011		
Hour (h)	3447	Meter	Working
Serial Number	54567B		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Breaker Pipings


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		475		

Note for External Appearance
The canopy is partly damaged



Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
- Quick hitch
- Oil oozing from the swing cylinder




Note for Undercarriage




Engine	
Model	3-3TNV82A
Serial Number	86775
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
The seat is partly torn



Note for Engine



Admin No. 2019010050