



# Inspection Report

Inspection Date: 2023/11/24

## Wheel Loader

### General Information

|                      |          |
|----------------------|----------|
| <b>Maker</b>         | TCM      |
| <b>Model Number</b>  | SD25T8   |
| <b>Year</b>          | 2010     |
| <b>Hour (h)</b>      | 7297     |
| <b>Serial Number</b> | 58F01126 |

### Note for External Appearance

- The covers are rusty and decayed



### Upper Structure

|                                  |             |
|----------------------------------|-------------|
| <b>Lift Arm Cylinder (Left)</b>  | No oil leak |
| <b>Lift Arm Cylinder (Right)</b> | No oil leak |
| <b>Bucket Cylinder (Left)</b>    | No oil leak |
| <b>Bucket Cylinder (Right)</b>   | No oil leak |

### Note for Upper Structure



### Undercarriage

|                    |             |
|--------------------|-------------|
| <b>Front Accel</b> | No oil leak |
| <b>Rear Accel</b>  | No oil leak |

### Note for Operating Component

- The brake is weak  
- The seat is partly torn



### Engine

|                         |               |
|-------------------------|---------------|
| <b>Model</b>            |               |
| <b>Serial Number</b>    |               |
| <b>Engine Oil Leak</b>  | No oil leak   |
| <b>Engine Oil Gauge</b> | OK            |
| <b>Exhaust Color</b>    | White         |
| <b>Blow-by</b>          | No            |
| <b>Engine Sound</b>     | OK            |
| <b>Water Pump</b>       | No water leak |
| <b>Radiator</b>         | OK            |

### Note for Undercarriage



### Documents

|  |    |
|--|----|
| <b>Automobile Inspection Certificate</b> | No |
|--|----|

### Note for Engine

- White exhaust smoke



Admin. No. 3000053442

\*This report is only for your reference. We are not responsible for the actual condition of checked item.