

Inspection Report

Inspection Date: 2017/08/08

Excavators

General Information		
Maker	YANMAR	
Model Number	B2-5	
Year	2005	
Hour (h)	3703 Meter	Working
Serial Number	55865B	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	riay
Boom	Left	No	No	Small
	Right	N/A	N/A	Sman
Arm		No	No	Big
Bucket		Oil oozing	No	Big
Bucket Size (mm)		420		

Undercarriage

Undercarnage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	250	250
Idler	ОК	ОК
Sprocket	ОК	ОК
Pin Bush	ОК	ОК
Upper Roller	ОК	ОК
Track Roller	ОК	ОК
Shoe Link	ОК	ОК

Engine	
Model	3TNV76-BX
Serial Number	12122
Engine Oil Leak	No oil leak
Engine Oil Gauge	ОК
Radiator	Unchecked
Exhaust Color	Normal
Blow-by	No
Engine Sound	ОК
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	N/A
Multi Lever	No oil leak

Options - CNP - Speed changer - Multilever - Blade - EPA


Note for External Appearance

Repainted



Note for Upper Structure Complete washing not applicable (bucket)

Note for Undercarriage	



Note for Engine



Admin No.

2017080092

*This report is only for your reference. We are not responsible for the actual condition of checked item.