



# Inspection Report

Inspection Date: 2018/06/16


## Excavators

General Information			
Maker	YANMAR		
Model Number	ViO20-3		
Year	2006		
Hour (h)	3208	Meter	Working
Serial Number	32876B		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		410		

Note for External Appearance
<ul style="list-style-type: none"> <li>- The canopy is partly cracked</li> <li>- The right and left covers have some dents</li> <li>- The body is partly painted</li> </ul>




Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	250	250
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	NG	NG
Shoe Link	OK	OK

Note for Upper Structure




Note for Undercarriage
Oil oozing from one of the left lower rollers and one of the right lower rollers



Engine	
Model	3TNV76-P
Serial Number	24174
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 2018060902