



Inspection Report

Inspection Date: 2021/05/21

Excavators

General Information

Maker	KOBELCO		
Model Number	SK200LC-1		
Year	1992		
Hour (h)	1905	Meter	Working
Serial Number	YQ-01528		

Options

- | | |
|--------------|-------------------|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	No	No	
Arm		Oil oozing	No	Small
Bucket		No	No	Big
Bucket Size (mm)	850			

Note for External Appearance

- The body is partly damaged and rusty



Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	800	800
Idler	NG	NG
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- 15-meter super long front
- 4 sides of the arm have been reinforced
- The right blinker is damaged and cracked



Note for Undercarriage

- The idlers are worn



Engine

Model	6D31T
Serial Number	6D31-025376
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Oil oozing
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000031454