



Inspection Report

Inspection Date: 2021/05/20

Carrier Dump

General Information

Maker	KOMATSU
Model Number	CD30R-1
Year	1997
Hour (h)	783
Serial Number	1104

Engine

Model	4D88E-3D
Serial Number	12972
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for External Appearance

- The body is rusty and decayed
- The VIN stamp on the body was not found

Note for Control Panel

Note for Engine

Other Information

- Rotation dump
- 320 rubber track

Admin. No. 3000031322

*This report is only for your reference. We are not responsible for the actual condition of checked item.