



Inspection Report

Inspection Date: 2017/04/11

Generator

General Information

Maker	DENYO
Model Number	DCA-110SPN
Year	1992
Hour (h)	1157
Serial Number	36361**

Note for External Appearance

--

Engine

Model	FE6T05
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

--

Note for Engine

--

Admin. No. 2017040022

*This report is only for your reference. We are not responsible for the actual condition of checked item.