

Excavator

| General Information | |
|---------------------|------------|
| Maker | KOBELCO |
| Model Number | SK70SR-1ES |
| Year | 2005 |
| Hour (h) | 4906 |
| Serial Number | YT0 |

| Upper Structure | |
|-----------------------|-------------------|
| Boom Cylinder (Left) | No oil leak |
| Boom Cylinder (Right) | No oil leak |
| Arm Cylinder | No oil leak |
| Bucket Cylinder | No oil leak |
| Bucket Width (mm) | 650 |
| Swing | Backlash and play |

Undercarriage

| v | | | |
|-----------------|-------------|-------|--|
| Swivel Joint | No oil leak | | |
| | Left | Right | |
| Shoe Width (mm) | 450 | 450 | |
| Idler | OK | OK | |
| Sprocket | OK | OK | |
| Pin Bush | OK | OK | |
| Upper Roller | OK | OK | |
| Track Roller | OK | OK | |
| Shoe Link | ОК | ОК | |

| Engine | |
|------------------|---------------|
| Model | 4JG1 |
| Serial Number | 289675 |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | ОК |
| Radiator | ОК |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | No oil leak |

Note for External Appearance

Equipped with pipings and multi lever

Note for Upper Structure

- The bucket pin has a play The arm has a dent



Note for Undercarriage



Note for Operating Component



| Note for Engine | |
|-----------------|--|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |