



Inspection Report

Inspection Date: 2021/05/22

Excavators

General Information

Maker	KOMATSU		
Model Number	PC228US-3T1		
Year	2008		
Hour (h)	3304	Meter	Working
Serial Number	KMTPC204P02025003		

Options

- | | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| | - Pippings |
| - Arm Crane | |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		Oil oozing	Yes	Big
Bucket Size (mm)	1030			

Note for External Appearance

- The body is repainted, partly damaged, rusty, and has some dents



Undercarriage

Shoe Type	Steel	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	600	600
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	NG	NG
Shoe Link	OK	OK

Note for Upper Structure

- Oil oozing from the control valve
- Oil adheres to the upper part of the hydraulic tank



Note for Undercarriage

- Oil oozing from 2 of the left lower rollers and 2 of the right lower rollers



Engine

Model	SAA6D107E
Serial Number	26521539
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The speed changer is not working



Note for Engine



Admin No. 3000031323