



Inspection Report

Inspection Date: 2022/11/10

Excavators

General Information

Maker	KOMATSU		
Model Number	PC10UU-5		
Year	2011		
Hour (h)	965	Meter	Working
Serial Number	KMTPC194C04015358		

Options

	- Speed changer
- Blade	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	320			

Note for External Appearance

- The body chassis number is unchecked
- Repainted



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	180	180
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

- The width between the shoes is adjustable, but operation is unchecked



Engine

Model	2D70E-5SBB
Serial Number	03067
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn



Note for Engine



Admin No. 3000043668