



Inspection Report

Inspection Date: 2022/11/25


Excavators

General Information			
Maker	HITACHI		
Model Number	ZX55UR-3		
Year	2014		
Hour (h)	4252	Meter	Working
Serial Number	HCM1YG00C00035831		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		590		

Note for External Appearance
- The covers have some dents



Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	400	400	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
- Rotation is not smooth (has play and backlash)




Engine	
Model	V2403
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak


Note for Undercarriage



Note for Operating Component
- The seat is torn



Note for Engine
- The battery is weak



Admin No. 300044007