



Inspection Report


Inspection Date: 2017/09/15

Excavators


General Information			
Maker	YANMAR		
Model Number	ViO20-3		
Year	2003		
Hour (h)	3651	Meter	Working
Serial Number	25816B		


Options	
- CNP	- Speed changer
- Blade	- Breaker Pipings
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		420		


Note for External Appearance
Repainted



Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	250	250	
Idler	NG	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
- The attachment in the picture is not for sale
- A standard bucket will be attached before shipment
- The tip of the arm has some dents


Note for Undercarriage
The right rubber shoe is loose


Engine	
Model	3TNE74-ENBV
Serial Number	N14019
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No confirmation of movement
Multi Lever	-

Note for Operating Component
- The multi lever unchecked
- The roof of the cabin has some scratches and is partly cracked


Note for Engine


Admin No. 2017090390