



Inspection Report


Inspection Date: 2019/02/16

Excavators


General Information			
Maker	SUMITOMO		
Model Number	SH200-5		
Year			
Hour (h)	6995	Meter	Working
Serial Number	BH1924		


Options	
- CAB	- Speed changer
- Multilever	- Air conditioner

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Big
	Right	No	No	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)	1020			


Note for External Appearance



Undercarriage			
Shoe Type	Steel		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	700	700	
Idler	NG	OK	
Sprocket	OK	NG	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
The bucket has been reinforced


Note for Undercarriage
The sprockets are worn


Engine	
Model	4HK1
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	White
Exhaust Color	White
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component


Note for Engine
The engine produces white exhaust smoke for about first 10 minutes


Admin No. 2019020074