



Inspection Report

Inspection Date:

Carrier Dump

General Information

Maker	YANMAR
Model Number	C30R-2B
Year	2014
Hour (h)	
Serial Number	27776

Note for External Appearance

- The body is rusty and corroded and have scratches
- The body chassis number (VIN stamp) is unidentified due to repainting

Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

- The hour meter is unknown

Note for Engine

Other Information

Admin. No. 3000089906

*This report is only for your reference. We are not responsible for the actual condition of checked item.