



Inspection Report

Inspection Date: 2017/03/06

Excavators

General Information

Maker	KUBOTA		
Model Number	U-40-3S		
Year	2006		
Hour (h)	3830	Meter	Working
Serial Number	307**		

Options

- CNP
- Multilever
- Blade
- Speed changer

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)	545			

Note for External Appearance

Repainted



Undercarriage

Shoe Type	Rubber	
Swing Circle	Oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage



Shoe Link

Model	V2203KA
Serial Number	06A4881
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 2017050043