



Inspection Report

Inspection Date: 2026/07/21

Excavators

General Information

#ERROR!	HITACHI		
Model Number	ZX75US-5B		
Year	2016		
Hour (h)	4327	Meter	Working
Serial Number	HCMDEPA0C00071250		

Options

- CAB	- Speed changer
	- Air conditioner
- Blade	- Pippings
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		650		

Note for External Appearance

- No caution plate
- The body has scratches and rust
- The battery is flat; the machine worked normally with the booster cables



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- No bucket side cutters



Note for Undercarriage

- The rubber pads are worn
- Some Rubber pads are missing



Engine

Model	4TNV98C-WHBW5
Serial Number	37118
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for Operating Component

- The air conditioner is broken



Note for Engine



Admin No. 3000077892

*This report is only for your reference. We are not responsible for the actual condition of checked item.