



Inspection Report

Inspection Date: 2024/08/14

Roller

General Information

Maker	KOMATSU
Model Number	JV40DW-3
Year	1996
Hour (h)	5161
Serial Number	JV40DW3E-5113

Engine

Model	3D84E-36
Serial Number	06185
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK


Note for External Appearance

- Repainted



Note for Undercarriage

- Front and rear: steel tire
- Vibrating operation is in normal condition.



Note for Operating Component



Note for Engine



Admin. No. 3000062784

*This report is only for your reference. We are not responsible for the actual condition of checked item.