



Inspection Report

Inspection Date: 2018/10/04

Excavators

General Information

Maker	KUBOTA		
Model Number	RX-306		
Year	2009		
Hour (h)	4970	Meter	Working
Serial Number	10142		

Options

- CNP
- Multilever
- Blade
- Arm Crane

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)	420			

Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Engine

Model	D1703
Serial Number	9S1958
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Oil leak
Multi Lever	No oil leak

Note for External Appearance



Note for Upper Structure

Complete washing is not applicable (bucket)



Note for Undercarriage

Oil leak from around the swivel



Note for Operating Component



Note for Engine



Admin No. 2018100020