

## **Inspection Report**

**Inspection Date:** 

#N/A

| General Information |        |
|---------------------|--------|
| Maker               | AICHI  |
| Model Number        | SR12B  |
| Year                | 2004   |
| Hour (h)            | 4807   |
| Serial Number       | 682381 |

## Engine

| Engine           |               |
|------------------|---------------|
| Model            | 3LD PA-49     |
| Serial Number    | 3LD-441449    |
| Engine Oil Leak  | No oil leak   |
| Engine Oil Gauge | ОК            |
| Exhaust Color    | Normal        |
| Blow-by          | No            |
| Engine Sound     | ОК            |
| Radiator         | ОК            |
| Water Pump       | No water leak |
| Injection Pump   | No fuel leak  |

## Note for External Appearance

Maximum working height: 12m
Crawler type

## Note for Control Panel

Note for Engine

- EPA

Other Information

Admin. No. 3000040369

\*This report is only for your reference. We are not responsible for the actual condition of checked item.