



# Inspection Report

Inspection Date: 2019/07/10

## Excavators

### General Information

<b>Maker</b>	KOBELCO		
<b>Model Number</b>	SK210D-9		
<b>Year</b>	2014		
<b>Hour (h)</b>	3226	<b>Meter</b>	Working
<b>Serial Number</b>	YN13-71129		

### Options

- |              |           |
|--------------|-----------|
| - CAB        | - Pipings |
| - Multilever |           |
| - Arm Crane  |           |

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Unchecked
Bucket Size (mm)	1245			

### Note for External Appearance



### Undercarriage

<b>Shoe Type</b>	Steel	
<b>Swing Circle</b>	No oil leak	
	<b>Left</b>	<b>Right</b>
Shoe Width (mm)	600	600
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

### Note for Upper Structure

- Skeleton bucket
- A standard bucket is not for sale



### Note for Undercarriage

A part of the left shoe has a kink



### Engine

<b>Model</b>	J05E-TJ
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	Normal
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component



### Note for Engine



Admin No. 2019070558