



Inspection Report

Inspection Date: 2019/02/18


Excavators

| General Information | | | |
|----------------------|--------|--------------|---------|
| Maker | YANMAR | | |
| Model Number | B7-5A | | |
| Year | 2007 | | |
| Hour (h) | 5461 | Meter | Working |
| Serial Number | 58254B | | |

| Options | |
|--------------|-------------------|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |
| - Blade | |
| - Arm Crane | |
| - EPA | |


| Upper Structure | | | | |
|-------------------------|--------------|----------|--------------|-------|
| | | Cylinder | | Play |
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | Small |
| | Right | N/A | N/A | |
| Arm | | No | No | No |
| Bucket | | No | No | Small |
| Bucket Size (mm) | | 640 | | |

Note for External Appearance



| Undercarriage | | | |
|------------------------|------------------------------|--------------|--|
| Shoe Type | Steel shoes with rubber pads | | |
| Swing Circle | No oil leak | | |
| | Left | Right | |
| Shoe Width (mm) | 450 | 450 | |
| Idler | OK | OK | |
| Sprocket | OK | OK | |
| Pin Bush | OK | OK | |
| Upper Roller | OK | OK | |
| Track Roller | OK | OK | |
| Shoe Link | OK | OK | |

Note for Upper Structure




Note for Undercarriage



| Engine | |
|-------------------------|---------------|
| Model | 4TNV98-XBV |
| Serial Number | |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | Normal |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | Unchecked |
| Multi Lever | No oil leak |

Note for Operating Component
The seat is partly torn



Note for Engine



Admin No. 2019020347