



# Inspection Report


Inspection Date: 2018/04/13

## Excavators


| General Information  |            |              |         |
|----------------------|------------|--------------|---------|
| <b>Maker</b>         | KOBELCO    |              |         |
| <b>Model Number</b>  | SK30SR-5   |              |         |
| <b>Year</b>          | 2007       |              |         |
| <b>Hour (h)</b>      | 3095       | <b>Meter</b> | Working |
| <b>Serial Number</b> | PW14-45058 |              |         |


| Options      |  |
|--------------|--|
| - CNP        |  |
| - Multilever |  |
| - Blade      |  |
| - EPA        |  |
| - Pipings    |  |

| Upper Structure  |       |          |              |       |
|------------------|-------|----------|--------------|-------|
|                  |       | Cylinder |              | Play  |
|                  |       | Oil Leak | Scratch/Rust |       |
| Boom             | Left  | No       | No           | No    |
|                  | Right | N/A      | N/A          |       |
| Arm              |       | No       | No           | Small |
| Bucket           |       | No       | No           | Small |
| Bucket Size (mm) |       | 450      |              |       |


| Note for External Appearance  |
|---|
|  |

| Undercarriage          |             |              |  |
|------------------------|-------------|--------------|--|
| <b>Shoe Type</b>       | Rubber      |              |  |
| <b>Swing Circle</b>    | No oil leak |              |  |
|                        | <b>Left</b> | <b>Right</b> |  |
| <b>Shoe Width (mm)</b> | 300         | 300          |  |
| <b>Idler</b>           | OK          | OK           |  |
| <b>Sprocket</b>        | OK          | OK           |  |
| <b>Pin Bush</b>        | OK          | OK           |  |
| <b>Upper Roller</b>    | OK          | OK           |  |
| <b>Track Roller</b>    | OK          | OK           |  |
| <b>Shoe Link</b>       | OK          | OK           |  |

| Note for Upper Structure  |
|---|
|  |

| Note for Undercarriage  |
|---|
| The rubber shoes have deteriorated over time and are worn                             |
|  |

| Engine                  |               |
|-------------------------|---------------|
| <b>Model</b>            | 3TNV88-BPYB   |
| <b>Serial Number</b>    |               |
| <b>Engine Oil Leak</b>  | No oil leak   |
| <b>Engine Oil Gauge</b> | OK            |
| <b>Radiator</b>         | OK            |
| <b>Exhaust Color</b>    | Normal        |
| <b>Blow-by</b>          | No            |
| <b>Engine Sound</b>     | OK            |
| <b>Hydraulic Pump</b>   | No oil leak   |
| <b>Water Pump</b>       | No water leak |
| <b>Oil Cooler</b>       | No oil leak   |
| <b>Motor</b>            | Unchecked     |
| <b>Multi Lever</b>      | No oil leak   |

| Note for Operating Component  |
|---|
|  |

| Note for Engine   |
|---|
|  |

Admin No. 2018040327