



Inspection Report

Inspection Date: 2024/08/02

Excavators

General Information

| | | | |
|----------------------|-------------------|--------------|---------|
| Maker | KOMATSU | | |
| Model Number | PC30UU-5 | | |
| Year | 2015 | | |
| Hour (h) | 2470 | Meter | Working |
| Serial Number | KMTPC219VFE019094 | | |

Options

| | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | |

Upper Structure

| | | Cylinder | | Play |
|------------------|-------|------------|--------------|-------|
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | Small |
| | Right | N/A | N/A | |
| Arm | | Oil oozing | No | Small |
| Bucket | | No | No | Big |
| Bucket Size (mm) | 410 | | | |


Note for External Appearance




Undercarriage

| | | |
|---------------------|-------------|--------------|
| Shoe Type | Rubber | |
| Swing Circle | No oil leak | |
| | Left | Right |
| Shoe Width (mm) | 300 | 300 |
| Idler | OK | OK |
| Sprocket | OK | OK |
| Pin Bush | OK | OK |
| Upper Roller | OK | OK |
| Track Roller | OK | OK |
| Shoe Link | OK | OK |

Note for Upper Structure



Note for Undercarriage



Engine

| | |
|-------------------------|---------------|
| Model | 3D88E-6BPCD |
| Serial Number | 33381 |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | No oil leak |

Note for Operating Component



Note for Engine



Admin No. 3000061519