



Inspection Report

Inspection Date: 2018/06/14


Excavators

General Information			
Maker	YANMAR		
Model Number	ViO50-3		
Year	2004		
Hour (h)	3655	Meter	Working
Serial Number	30756B		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		610		

Note for External Appearance
- No caution plate
- The right cover has some dents




Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	390	390
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
Rotation is unchecked because there was not an enough space for inspection




Note for Undercarriage
- Traveling motion is unchecked
- The left rubber shoe has deteriorated over time, is worn, and partly cracked




Engine	
Model	4TNV88-XBV
Serial Number	8938
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	White
Exhaust Color	White
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
- The seat is partly torn
- The arm crane monitor is broken and numbers can't be read



Note for Engine
A little white smoke



Admin No. 2018061077